



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 Mar 2022, 12:00:25
Transaction Number	82437333 (CC10006)	Queue Number	312309



Chassis Number	WDDNG56X79A259827
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	S 350
Model Year	2009
Color	Black
Mileage	322231 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	FRONT RIGHT SIDE & REAR LEFT SIDE REPAINTED	أبواب
01.B Bonnet	REPAINTED	غطاء المحرك
01.C Paint	BODY PORTION REPAINTED MINOR DENT, SCRATCHES	الصبغ
01.D Floor	UNDER FLOOR COVER DAMAGED	الارضية
01.E Windshield	REAR WINDSHIELD TINT FADED	زجاج
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK , REFITTED, JERKING	حالة الجير النظري
02.C Gear Box Mount	REAR MOUNT RUBBER CRACKED	كرسي الجير
03 Interior Condition		الحالة الداخلية
03.A Power Window Switch	RIGHT BOTH SIDE DOOR NOT WORKING	مفتاح النافذه
03.B Other	CONSOLE BOX LOCK DAMAGED	اخرى
03.C Mirror	LEFT SIDE NOT WORKING	المرآيا
03.D AC Condition	OK	المكيف
03.E Steering Wheel and control buttons	WORN OUT, NOISY	عجلة القيادة وازرار التحكم

DEFECT	REMARKS	
04 Tires and Rims Condition		الاطارات
04.A Front Tyre	BOTH SIDE 2019 WORN OUT	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2019 WORN OUT	الاطار الخلفي
05 Engine Condition		المحرك
05.A Visual Engine Condition	MINOR OIL LEAK, REFITTED	حالة المحرك النظري
06 Steering Condition		المقود
06.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
06.B Axel	REAR BOTH SIDE BOOT CUT	اكسلات
07 Battery Condition		حالة البطارية
07.A Battery bracket	COVER MISSING	حامل البطارية
08 Seats Condition		المقاعد
08.A Seat Belt	REAR LEFT SIDE NOT WORKING	حزام الأمان
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES MINOR CRACKED	ازرع
10 Chassis Condition		الشاسي
10.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.