CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2981764
Transaction Date	13 Nov 2026, 15:07:30
Site Name	840 - Emirates Auctions
Transaction Number	27030207 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN6BE6BSXF*******
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2015
Color	White
Mileage	116795 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,EXCEPT ROOF,MINOR DENT SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.F Bumper	MISALIGN PORTION CRACK,TOWING HOOK COVER MISSING	دعامية
01.G Bonnet	GRILL LOOSE FIX BY CABLE TIE	غطاء المحرك
01.H Sign of front accident	FRONT RIGHT SIDE DOOR POST AREA REPAIRED	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL DENT	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS PORTION GETTING RUSTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FRONT RIGHT SIDE CROSS MEMBER BRACKET REPAIRED	اخري
03 Engine Condition		المحرك
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Engine Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	FRONT EXTRA COVER,REAR SEATS MISSING CABIN MODIFIED	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 DRY CRACK	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2020 CRACKED EXPIRED,RIGHT 2023	الاطار الخلفي
06.C Spare Tire &Tools	SPARE TIRE MISSING	الاطار الاحتياطي و العدة
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE LENS FADED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE CRACKED	الضوء الخلفي
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	SIGN OF LEAK	ممتص الصدمات
08.B Leaf Spring	MISALIGN , BUSHES DRY CRACK	
08.C Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY	اخري
09.B AC Condition	OK,SWITCH PORTION DAMAGED	المكيف
09.C Power Window Switch And Glass	RIGHT SIDE SWITCH PANEL LOOSE	مفتاح النافذه و الزجاج
09.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB GETTING WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر

wecare@carscheck.ae