



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>01 Nov 2022, 13:32:35</b>
Transaction Number	<b>81444796 (CC10009)</b>	Queue Number	<b>615874</b>



Chassis Number	<b>JN8AY25Y3A9001992</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Patrol</b>
Model Year	<b>2010</b>
Color	<b>Blue</b>
Mileage	<b>120491 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	FRONT BOTH SIDE FENDER FRAME CUT REWELDED (MODIFIED SHAPE CHANGED)	مدكار
01.B Trunk	REFITTED,MODIFIED	صندوق
01.C Bumper	MODIFIED	دعامية
01.D Vehicle Color	CHANGE WHITE TO BLUE	لون المركبة
01.E Paint	BODY TOTALLY REPAINTED PORTION REPAIRED , MINOR DENTS SCRATCHES(BODY SHAPE CHANGE)	الصبغ
01.F Bonnet	REFITTED,MODIFIED	غطاء المحرك
01.G Vehicle Model	VEHICLE SHAPE CHANGED TO NEM MODEL	طرز المركبة
01.H Floor	REAR BOTH SIDE QUARTER PANEL TAIL LIGHT AREA CUT (MODIFIED)	الارضية
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE 2021,	الاطار الخلفي
02.B Front Tyre	BOTH SIDE 2021,	الاطار الامامي
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	REAR NOT WORKING	المكيف
03.B Dash Board	LEATHER PORTION LOOSE	لوحة القيادة

DEFECT	REMARKS	
03.C Other	INTERIOR MODIFIED	اخرى
03.D Mirror	RIGHT SIDE AUTO FOLDING NOT WORKING	المرآيا
03.E Roof Light	CONSOLE BOX LOOSE	أنارة السقف
03.F Roof Ceiling	LOOSE	بطانه السقف
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.B Head Light	MODIFIED	الاضاءة الرئيسية
04.C Tail Light	MODIFIED	الانارة
<b>05 Transmission Condition</b>		<b>الجير</b>
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
<b>06 Seats Condition</b>		<b>المقاعد</b>
06.A Seat Condition	DRIVER SEAT MINOR LOOSE,ADJUSTMENT BUTTON MISSING	حالة المقاعد
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	MINOR OIL LEAK	حالة المحرك النظرى
08.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>09 Suspension System</b>		<b>ممتص الصدمات</b>
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	CHASSIS FRAME COMPLETELY RUST PROOFED, PORTION RUSTY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



✓ PASS

Transfer Certificate :	61327051
Chassis No :	JN8AY25Y3A9001992
Vehicle Make :	NISSAN.
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	120492 Kms.
Origin : Japan	Model Year : 2010
Gear Type : Automatic	Engine Size : 3500 CC
Engine No : VK56686067Z	Horse 95
Axles No : 2	Power :
No Of 4	Cylinders : 8
Doors :	No Of Seats : 8
G. V. W. : 2200 Kgs.	Empty 1800 Kgs.
	Weight :

Certificate Number :	5-TAS-2022-18059937		
Inspection Date :	09-11-2022		
Certificate Print Date :	09-11-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	12 min 32 sec		
Appointment Ref Number :	--		
Start Time :	15:40	End Time :	15:53
Lane :	03	Token No. :	189
Attempt :	1	Prints No. :	1

## Carbon footprint



Thank you! You are environment protector

## Estimated Vehicle Consumption (Rate last 12 Months)

1352 KM	140 L	478 AED	0.4 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

## Parameter Readings

Service brake imbalance on front axle 27 %	Service brake imbalance on rear axle 6 %	Parking brake imbalance between LHS and RHS 8 %	Vehicle on Petrol HC Reading 40 PPM VOL
Vehicle on Petrol CO Reading 0.01 %			

## Inspection Findings

Discrepancies	Old Value	New Value	Verified
Vehicle Model - Registration Incorrect Model - Does Not Require Document	PATROL	PATROL	
Vehicle Make - Registration Incorrect Make - Does Not Require Document	NISSAN.	NISSAN	
Paint Change Color	White	Blue	
Engine Size Discrepancy in Engine Size	3500	5600	

Inspection Remarks: front bumper, bumper frame, bulk head repaired, minor engine oil leak.

## Payment Details

Inspection Performed by 35063	Payment Method Cash	Transaction Number 18059937	Service Fees AED 170 Collected on 09/11/2022
Parking Slot No --	Service Name Registration Test	Attempt 1	Received by Sittu Paloth Sreesan Paloth

- 1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.  
2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

