



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>04 Aug 2022, 14:37:19</b>
Transaction Number	<b>56487770 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>MDHBN7ADXLG714606</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Nissan</b>
Model	<b>Sunny</b>
Model Year	<b>2020</b>
Color	<b>White</b>
Mileage	<b>73177 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار
01.B Trunk	PORTION REPAIRED,REPAINTED	صندوق
01.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
01.D Sign of back accident		وجود مؤشر لحادث في الخلف
01.E Sign of front accident		وجود مؤشر لحادث في المقدمة
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A AC Condition	OK	المكيف
<b>03 Transmission Condition</b>		<b>الجير</b>
03.A Road Test	NOT CHECK	فحص علي الطريق
03.B Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
03.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
<b>04 Tires and Rims Condition</b>		<b>الاطارات</b>
04.A Rear Tyre	BOTH SIDE 2019/2022	الاطار الخلفي
04.B Front Tyre	BOTH SIDE 2022	الاطار الامامي

DEFECT	REMARKS	
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	LOWER ARM BUSHES CRACKED	ازرع
05.B Ball Joint	BOOT CUT	مفصل كروي
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
06.B Mount	MOUNT RUBBER CRACKED	كرسي
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
<b>08 Steering Condition</b>		<b>المقود</b>
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.