



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **16 May 2023, 12:53:33**
 Transaction Number **41531459 (CC10006)** Queue Number **716303**



Chassis Number **JTGRX12PXF8044636**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Van**
 Model Year **2015**
 Color **White**
 Mileage **262164 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **GCC Specification**

| DEFECT | REMARKS | |
|----------------------------------|---|--------------------------|
| 01 Transmission Condition | | الجير |
| 01.A Gear Box Mount | BUSH CRACKED | كرسي الجير |
| 01.B Road Test | NOT CHECK | فحص علي الطريق |
| 01.C Visual Gear Box Condition | ,OIL LEAK REFITTED | حالة الجير النظري |
| 02 Lights | | الاضاءة |
| 02.A Tail Light | RIGHT SIDE COVER DAMAGED | الانارة |
| 02.B Warning Light | WARNING LIGHT ON IN DISPALY | ضوء تحذير |
| 03 Body | | جسم المركبة |
| 03.A Paint | BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION FADED ,PORTION RUSTY | الصبغ |
| 03.B Floor | BACK PANEL, QUATER PANEL, COMPARTMENT, REPAIRED | الارضية |
| 03.C Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 03.D Sign of back accident | | وجود مؤشر لحادث في الخلف |
| 03.E Bumper | MISALIGN,PORTION DAMAGE. | دعامية |
| 03.F Vehicle Model | HIACE | طراز المركبة |
| 04 Seats Condition | | المقاعد |

| DEFECT | REMARKS | |
|---|---------------------------------|----------------------------|
| 04.A Seat Condition | PORTION DAMAGED | حالة المقاعد |
| 05 Interior Condition | | الحالة الداخلية |
| 05.A Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |
| 05.B AC Condition | NOT WORKING | المكيف |
| 05.C Sun Visor | RIGHT SIDE MISSING | حاجب الشمس |
| 06 Chassis Condition | | الشاسي |
| 06.A Chassis | FRONT EXTENSION DENT | الشاسيه |
| 07 Engine Condition | | المحرك |
| 07.A Mount | BUSHES CRACKED | كرسي |
| 07.B Smoke | BLACK | دخان |
| 07.C Visual Engine Condition | OIL WET,REFITTED | حالة المحرك النظري |
| 08 Steering Condition | | المقود |
| 08.A Steering Box | OIL LEAK | جهاز المقود |
| 08.B Tie Rod End | BOOT CUT | مؤخرة الرودادات |
| 09 Tires and Rims Condition | | الاطارات |
| 09.A Front Tyre | BOTH SIDE 2021,WORN OUT CRACKED | الاطار الامامي |
| 09.B Rear Tyre | BOTH SIDE 2021,WORN OUT CRACKED | الاطار الخلفي |
| 10 Suspension System | | ممتص الصدمات |
| 10.A Arms | LOWER ARM BUSHES CUT | ازرع |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.