

Queue Number

2579275

Transaction Date

25 Jul 2026, 12:44:05

Site Name

840 - Emirates Auctions

Transaction Number

49863617 (CC10013) (CC10019)



Vehicle Details

Chassis Number	JN6BE6DSXE*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2014
Color	White
Mileage	389280 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Bumper	MISALIGN, PORTION DAMAGED	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, WHEEL ARCH FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE REPAIRED GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Exhaust System

نظام العادم

05.A Other	DENT	اخرى
------------	------	------

06 Transmission Condition

الجير

Condition	Remarks	الحالة
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظرية للجير
06.B Road Test	NOT CHECK	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	2025 WORN OUT	الاطار الامامي
07.B Rear Tyre	2025 WORN OUT	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Leaf Spring	MISALIGN	اخري
09.C Other	ALL BUSHES DRY CRACK	
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY	اخري
10.B Mirror	CENTER MISSING	المرايا
10.C AC Condition	NOT WORKING	المكيف
10.D Dash Board	PORTION DAMAGED	لوحة القيادة
10.E Door Panel	PORTION DAMAGED PART MISSING	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB DUST COVER WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae