



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>26 Sep 2022, 17:20:55</b>
Transaction Number	<b>62825257 (CC10006)</b>	Queue Number	<b>596567</b>



Chassis Number	<b>MAJTK1BA5EAC56437</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Ecosport</b>
Model Year	<b>2014</b>
Color	<b>White</b>
Mileage	<b>207366 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Engine Condition</b>		<b>المحرك</b>
01.A Visual Engine Condition	AC BELT MISSING.	حالة المحرك النظري
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
<b>03 Interior Condition</b>		<b>الحاله الداخليه</b>
03.A AC Condition	NOT WORKING	المكيف
03.B Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.C Audio	ANTINA DAMAGED	صوتيات
<b>04 Lights</b>		<b>الاضاءة</b>
04.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04.B Other	TRANSMISSION MALFUNCTION LIGHT ON	اخرى
<b>05 Body</b>		<b>جسم المركبة</b>
05.A Trunk	PORTION REPAIRED,REPAINTED & NOT OPEN FOR CHECK	صندوق
05.B Fenders	FRONT RIGHT SIDE PORTION REPAIRED,REPAINTED	مدكار
05.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ

DEFECT	REMARKS	
05.D Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
05.E Sign of front accident		وجود مؤشر لحادث في المقدمة
05.F Other	FRONT RIGHT SIDE FENDER FRAME ,BULKHEAD REPAIRED.	اخرى
05.G Bumper	BUMPEWR FRAME REFITTED.	دعامية
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Visual Gear Box Condition	MAJOR JERKING,GEAR NOT SHIFTING PROPERLY	حالة الجير النظري
06.B Road Test	NOT CHECK	فحص علي الطريق
<b>07 Tires and Rims Condition</b>		<b>الاطارات</b>
07.A Rear Tyre	BOTH SIDE 2018 & CRACKED	الاطار الخلفي
07.B Front Tyre	BOTH SIDE 2018 & CRACKED	الاطار الامامي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.