

Queue Number 2836098

Transaction Date 06 Oct 2026, 13:43:13

Site Name
840 - Emirates AuctionsTransaction Number
58002759 (CC10010) (CC10010)

Vehicle Details

Chassis Number	MNTBD03S6C*****
Specification	GCC Specification
Make	Nissan
Model	Navara
Model Year	2012
Color	Brown
Mileage	521481 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED , RIGHT SIDE PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , DENT SCRATCHES PORTION RUSTY & HOLE	الصبغ
01.C Doors	FRONT BOTH SIDE REFITTED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MINOR DENT	الارضية
01.F Bumper	MISALIGN , MINOR SCRATCHES , DENT	دعامية
01.G Roof	BOTH SIDE TRAIL STRIP MISSING , GETTING RUSTY HOLE	السقف
01.H Bonnet	REPAINTED , REFITTED	غطاء المحرك
01.I Trunk	TAIL GATE REFITTED , MIS ALIGN	صندوق
01.J Vehicle Color	WHITE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETE RUSTY , PORTION DENT, MUDDY	الشاسيه
02.B Chassis Number	VIN GETTING RUSTY	رقم القاعدة

03 Engine Condition

المحرك

03.A Other	AIR FILTER HOSE DAMAGE	اخرى
03.B Engine Visual Condition	REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET , SHAKING	الحالة النظرية للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	FABRIC WORN OUT , BACK COVER DAMAGE	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , SIGN OF OIL WET , MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 , LEFT SIDE FUNCTURE	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2025 RIGHT SIDE 2023 BADLY DAMAGE	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	GETTING FADED	الاضاءة الرئيسية
07.B Tail Light	LEFT SIDE DAMAGE , CRACK	الضوء الخلفي
07.C Indicator & Hazard light	LEFT SIDE INDICATOR LIGHT COVER DAMAGE	الاشارات
07.D Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.E Fog light	FOG HOUSING MISSING	كشاف الضباب
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	MINOR OIL LEAK	ممتص الصدمات
09.B Leaf Spring	BUSHES CRACK	
10 Steering Condition		المقود
10.A Steering Boot	BOOT CUT	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE PANEL WORN OUT PORTION LOOSE , INTERIOR PARTS GETTING RUSTY SIGN OF FLOODED	اخرى
11.B Mirror	BOTH SIDE ADJUSTABLE CONTROL SWICTH NOT WORKING , CENTER VIEW MIRROR PORTION LOOSE	المرايا
11.C AC Condition	NOT COOLING	المكيف
11.D Roof Light	LEFT SIDE NOT WORKING	أنارة السقف
11.E Power Window Switch And Glass	MAIN CONTROL SWICTH PORTION WORN OUT , FRONT RIGHT SIDE CONTROL SWICTH NOT WORKING	مفتاح النافذه و الزجاج
11.F FLOOR Matting	DIRTY	فرش الأرضيه
11.G Audio	DISPLAY PANEL & CONTROL BUTTON WORN OUT , PORTION FADED	صوتيات
11.H Dash Board	DAMAGE , LEFT SIDE LOWER PORTION BUTTON DAMAGE	لوحة القيادة
11.I Roof Ceiling	REAR RIGHT SIDE GRAB HANDLE DAMAGE	بطانه السقف
11.J Sun Visor	FABRIC LOOSE	حاجب الشمس
11.K Door Panel	WORN OUT	لوحة بطانة الباب

Condition	Remarks	الحالة
11.L Steering Wheel and control buttons	WORN OUT , MISALIGN	عجلة القيادة وازرار التحكم
11.M Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات
11.N Engine Start Button	REMOTE WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae