



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	24 Jan 2023, 14:57:05
Transaction Number	18340498 (CC10006)	Queue Number	657809



Chassis Number	KNAFW6128C5440614
Engine Number	
Vehicle Class	Car
Manufacturer	Kia
Model	Cerato
Model Year	2012
Color	Grey
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Suspension System		ممتص الصدمات
01.A Shock Absorber	LEAK .	ممتص الصدمات
01.B Arms	LOWER ARM BUSHES CRACKED .	ازرع
02 Interior Condition		الحالة الداخليه
02.A AC Condition	NOT CHECKED .	المكيف
02.B Odometer reading	NOT CHECKED .	قراءة عداد المسافات
03 Seats Condition		المقاعد
03.A Seat Condition	SEAT PORTIONS DAMAGE .	حالة المقاعد
04 Lights		الاضاءة
04.A Fog light	LEFT SIDE MISSING .	كشاف الضباب
04.B Head Light	LENS FADED ,LEFT SIDE BROKEN ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
05 Steering Condition		المقود
05.A Tie Rod End	BALL JOINT BOOT CUT .	مؤخرة الرودادات
06 Tires and Rims Condition		الاطارات
06.A Rear Tyre	BOTH SIDE 2021 CRACKED.	الاطار الخلفي

DEFECT	REMARKS	
06.B Front Tyre	BOTH SIDE 2021 CRACKED .	الاطار الامامي
07 Body		جسم المركبة
07.A Paint	BODY PORTION REPAIRED ,REPAINTED ,DENTS SCRATCHES,PORTION RUSTY.	الصبغ
07.B Fenders	FRONT LEFT SIDE FENDER DAMAGE .	مدكار
07.C Bumper	MISALIGN ,PORTION DAMAGE .	دعامية
07.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
07.E Other	FRONT BULKHEAD ,RADIATOR SUPPORT BRACKET DAMAGED ,CRACKED ,	اخرى
07.F Floor	UNDER FLOOR RUNNING BOARD PORTION DENT .	الارضية
07.G Sign of front accident		وجود مؤشر لحادث في المقدمة
08 Transmission Condition		الجير
08.A Visual Gear Box Condition	REFITTED MINOR OIL LEAK .	حالة الجير النظرى
08.B Gear Box Mount	CRACKED .	كرسي الجير
08.C Road Test	NOT CHECKED .	فحص علي الطريق
09 Engine Condition		المحرك
09.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,OIL LEAK ,REFITTED	حالة المحرك النظرى
10 Chassis Condition		الشاسي
10.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.