



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 19 Jun 2022, 11:34:12 |
| Transaction Number | 52264574 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | WDDSJ4EB1EN038926 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Mercedes |
| Model | CLA 250 |
| Model Year | 2014 |
| Color | White |
| Mileage | 69243 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | USA Imported |

| DEFECT | REMARKS | |
|------------------------------------|--------------------------------------|------------------------|
| 01 Interior Condition | | الحاله الداخليه |
| 01.A Dash Board | LEATHER REPLACED | لوحة القيادة |
| 02 Tires and Rims Condition | | الاطارات |
| 02.A Front Tyre | BOTH SIDE 2015 EXPIRED ,CRACKED | الاطار الامامي |
| 02.B Rear Tyre | BOTH SIDE 2014/2015 EXPIRED, CRACKED | الاطار الخلفي |
| 03 Engine Condition | | المحرك |
| 03.A Visual Engine Condition | MINOR OIL LEAK & REFITTED | حالة المحرك النظري |
| 04 Transmission Condition | | الجير |
| 04.A Visual Gear Box Condition | REFITTED,POOR PICK UP | حالة الجير النظري |
| 04.B Road Test | NOT CHECK | فحص علي الطريق |
| 05 Chassis Condition | | الشاسي |
| 05.A Chassis | FRONT BOTH SIDE CHASSIS REPAIRED | الشاسيه |
| 06 Steering Condition | | المقود |
| 06.A Rack Pinion | REPAIRED, REWELDED | مسطرة المقود |

| DEFECT | REMARKS | |
|-----------------------------|--|----------------------------|
| 07 Body | | جسم المركبة |
| 07.A Bonnet | REPAIRED, REPAINTED & REFITTED | غطاء المحرك |
| 07.B Fenders | FRONT BOTH SID REPAINTED & REFITTED | مدكار |
| 07.C Paint | PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY | الصبغ |
| 07.D Sign of front accident | | وجود مؤشر لحادث في المقدمة |
| 07.E Bumper | LOWER BUMPER LOOSE | دعامية |
| 08 Seats Condition | | المقاعد |
| 08.A Seat Belt | REAR LEFT SIDE NOT WORKING | حزام الأمان |
| 09 Lights | | الاضاءة |
| 09.A Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 09.B Brake Light | RIGHT SIDE NOT WORKING | نور الفرامل |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

| | |
|--------------------------|-----------------------|
| Plate Details : | -- |
| Chassis No : | WDDJ4EB1EN038926 |
| Vehicle Make : | MERCEDES |
| Vehicle Model : | CLA250 |
| Vehicle Class : | Light Vehicle |
| Body Type : | SALOON |
| Fuel : | Benzene |
| Color : | White |
| Drive Direction : | -- |
| Dimensions : (H x W x L) | -- x -- x -- |
| Current Odometer : | 69247 Kms. |
| Origin : Germany | Model Year : 2014 |
| Gear Type : Automatic | Engine Size : 4700 CC |
| Engine No : NILL | Horse 208 |
| Axles No : 2 | Power : |
| No Of 4 | Cylinders : 4 |
| Doors : | No Of Seats : 5 |
| G. V. W. : 2100 Kgs. | Empty 1500 Kgs. |
| | Weight : |

| | | | |
|---------------------------|---------------------|--------------|-------|
| Certificate Number : | 5-TAS-2022-17083946 | | |
| Inspection Date : | 26-06-2022 | | |
| Certificate Print Date : | 26-06-2022 | | |
| Services : | Registration Test | | |
| Vehicle Testing Partner : | Tasjeel | | |
| Vehicle Testing Center : | Tasjeel Al Qusais | | |
| Total Time Taken : | 5 min 53 sec | | |
| Appointment Ref Number : | -- | | |
| Start Time : | 21:01 | End Time : | 21:07 |
| Lane : | 04 | Token No. : | 863 |
| Attempt : | 2 | Prints No. : | 1 |

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| | | | |
| 2842 KM | 293 L | 475 AED | 0.8 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Inspection Findings

| Discrepancies | Old Value | New Value | Verified |
|--|-----------|-----------|----------|
| Engine Size Discrepancy in Engine Size | 4700 | 2000 | |

Inspection Remarks: FRONT BOTH SIDE FRAME MEMBER REPAIRED HAVING CCM REPORT W/O 2022-06-26-8.

Payment Details

| | | | |
|----------------------------------|-----------------------------------|--------------------------------|---|
| Inspection Performed by 33723 | Payment Method Cash | Transaction Number 17083946 | Service Fees AED 70 Collected on 26/06/2022 |
| Parking Slot No -- | Service Name Registration Test | Attempt 2 | Received by Muhammad Essa Abdullah Ali AlBalooshi |

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.