



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	02 Aug 2022, 16:40:44
Transaction Number	53515939 (CC10006)	Queue Number	312309



Chassis Number	WBA7F2100HG713679
Engine Number	
Vehicle Class	Car
Manufacturer	BMW
Model	750LI
Model Year	2017
Color	Grey
Mileage	62066 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Tires and Rims Condition		الاطارات
01.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
02 Transmission Condition		الجير
02.A Visual Gear Box Condition	OK	حالة الجير النظري
02.B Road Test	NOT CHECK	فحص علي الطريق
03 Chassis Condition		الشاسي
03.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
04 Body		جسم المركبة
04.A Floor	UNDER BODY COVERED VISBALE AREA CHECK ONLY	الارضية
04.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
05 Steering Condition		المقود
05.A Axle	GRESE LEAK	اكسلات
06 Engine Condition		المحرك

DEFECT

REMARKS

06.A Visual Engine Condition

OK

حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.