

TEST CERTIFICATE

Site Number Transaction Number **840-Emirates Auctions** 29063134 (CC10006)

Transaction Date

06 Apr 2022, 15:00:45

Queue Number 312309

Chassis Number

1FM5K8D88DGC42672

Engine Number

Vehicle Class

Car Ford

Manufacturer

Model

Explorer

Model Year

2013

Color

Black

Mileage

195768 Km

Fuel Type

Petrol

No. Of Cylinders Specification

GCC Specification

REMARKS **DEFECT**

Of Transmission Condition	الجير

01.A Road Test	NOT CHECKED	فحص علي الطريق
01.B Gear Box Mount	MOUNT RUBBER RACKED	كرسي الجير
01.C Visual Gear Box	OK	حالة الجير النظرى
Condition		

02 Interior Condition الحاله الداخليه

02.A AC Condition ОК المكيف

03 Body جسم المركبة

03.A Doors	REPAIRED, REPAINTED	أبواب
03.B Trunk	REPAINTED	صندوق
03.C Bumper	REPAINTED, MISALIGN	دعامية
03.D Fenders	PORTION REPAIRED, REPAINTED	مدكار
03.E Paint	TOTALY REPAINTED, PORTION REPAIRED, EXCEPT ROOF,	الصبغ
	BONNET & DENTS, SCRATCHES ON BODY	

04 Tires and Rims Condition الاطارات

04.A Front Tyre	BOTH SIDE 2018	الاطار الامامي
04.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفى

DEFECT	REMARKS	
05 Chassis Condition		الشاصي
05.A Chassis	OK	الشاسيه
06 Engine Condition		المحرك
06.A Visual Engine Condition	OK	حالة المحرك النظرى
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY	دواسة الفرامل

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.