





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20035661	Plate Category	: PRIVATE
Transaction Date	: 24 JUN 2020 10:20:14	Plate Number	: 75629 EA
Queue Number	: 188457	Import Doc. Ref.	:
Chassis Number	: FZJ800075629	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 1994
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
16 Side Slip Test		فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed	فحص ميزانية الاطارات
VISUAL TEST:		
01 Lights		الانوار
01.02 - Tail Lights		الانوار الخلفية
01.06 - Brake Lights		انوار الفرامل
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.01 - Steering Box Oil, Adjust, Change		زيت صندوق عجلة القيادة
02.03 - Steering Wheel, Change, Repair		مقبض عجلة القيادة
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
05 Body		الهيكل
05.02 - Paint		الصبغ
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرآيا الجانبية
06.14 - Transmission Condition		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20035661	Plate Category	: PRIVATE
Transaction Date	: 24 JUN 2020 10:20:14	Plate Number	: 75629 EA
Queue Number	: 188457	Import Doc. Ref.	:
Chassis Number	: FZJ800075629	Manufacturer/Model	: TOYOTA/LAND CRUISER
Engine Number	:	Model Year	: 1994
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.06 - Chassis Ok	OK	الشاسي جيد
09.25 - Body Repainted		أثر صيغ في المركبة
The Test Certificate Shows the test Result at the time of inspection only.		