CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934094
Transaction Date	03 Nov 2026, 16:59:39
Site Name	840 - Emirates Auctions
Transaction Number	52892594 (CC10026) (CC10026)



Vehicle Details

Chassis Number	5TDYK3DC9G*******
Specification	Imported
Make	Toyota
Model	Sienna
Model Year	2016
Color	Silver
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES , PORTION FADED , PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENTS, MUDDY	الارضية
01.D Sign of front accident	FRONT BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS END PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Mount	UPPER MOUNT BUSHES CUT	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGE , REAR SEAT MISSING	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE CRACK & WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
09.B AC Condition	NOT CHECK	المكيف
09.C FLoor Matting	DIRTY	فرش الأرضيه
09.D Dash Board	PORTION DAMAGE	لوحة القياده
09.E Roof Ceiling	DAMAGE	بطانه السقف
09.F Door Panel	PORTION DAMAGE	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	PORTION WORN OUT , SHIFTER LOCK COVER MISSING	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae