





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20408817	Plate Category	: PRIVATE
Transaction Date	: 29 JUL 2020 11:47:58	Plate Number	: 813116 EA
Queue Number	: 201954	Import Doc. Ref.	:
Chassis Number	: 1N4AA5AP4BC813116	Manufacturer/Model	: NISSAN/MAXIMA
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights		الانوار الامامية
		LEFT HEADLIGHT BRACKET REPAIRED
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.10 - Ties Rods, Bushes, Center Link, Left And Right		ربلات ذراع التوجيه
		TIE ROD BOOTS CRACK
02.13 - Stub Axle Assemblies, Boots		المحور
		LEFT INNER AXLE BOOT CRACK
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
		LOWER CONTROL ARM BOOTS / SWAY BAR STABILISER LINK ROD BOOTS CRACK
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
		ALL TIRES DOT 2017
04.07 - Rims		الرنجات
		SCRATCHES
05 Body		الهيكل
05.02 - Paint		الصبغ
		BODY SCRATCHES & DENTS
05.04 - Fenders		المدكار
		FRONT RIGHT FENDER REPAIRED
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
		FRONT WINDSHIELD REPLACED
06 General Items		الاشياء العامة
06.14 - Transmission Condition		حالة ناقل الحركة
		REFITTED / SLIGHT INITIAL SHIFT SHOCK
06.16 - Engine Condition, Smoke		حالة المحرك - الدخان
		REFITTED/ OIL LEAK
07 Remarks		ملاحظات
07.04 - Others		ملاحظات اخرى
		262393 KMS
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		بحاجة الى ميزانية العجلات
09.06 - Chassis Ok		الشاصي جيد
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 20408817	Plate Category	: PRIVATE
Transaction Date	: 29 JUL 2020 11:47:58	Plate Number	: 813116 EA
Queue Number	: 201954	Import Doc. Ref.	:
Chassis Number	: 1N4AA5AP4BC813116	Manufacturer/Model	: NISSAN/MAXIMA
Engine Number	:	Model Year	: 2011
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

09.18 - A/C Not Cooling		عطل في المكيف
09.24 - Digital Display Damaged/Warning Lights	TPMS/ ENGINE MALFUNCTION LIGHTS ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p>		