

Queue Number 2780342

Transaction Date 21 Sep 2026, 17:01:06

Site Name
840 - Emirates AuctionsTransaction Number
18208177 (CC10009) (CC10012)

Vehicle Details

Chassis Number	SJAAB1ZVXH*****
Specification	GCC Specification
Make	Bentley
Model	Bentayga
Model Year	2017
Color	Black
Mileage	153850 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COVERED NOT VISIBLE,COVER PORTION DAMAGED	الارضية
01.F Bonnet	PORTION REPAINTED	غطاء المحرك
01.G Trunk	REPAINTED , MISALIGN	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED, CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	STEAM WASH & REMOVE ALL UNDER COVER FOR RECHECK PROPERLY	اخرى

03 Engine Condition

المحرك

03.A Other	TOP COVER PORTION CRACKED	اخرى
03.B Engine Visual Condition	OIL LEAK REFITTED , SIGN OF OVER HEAT	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR OIL LEAK REFITTED JERKING	الحالة النظرية للجير
--------------------------------	---------------------------------	----------------------

Condition	Remarks	الحالة
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025 , LEFT SIDE WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	SWITCH PANEL LOOSE	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY	دواسة الفرامل
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION REFITTED	اخرى
09 Interior Condition		الحالة الداخليه
09.A AC Condition	OK	المكيف
10 Engine Cooling System		نظام تبريد المحرك
10.A Coolant tank	LOW COOLANT	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae