



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Jul 2022, 17:47:39
Transaction Number	17774659 (CC10006)	Queue Number	312309



Chassis Number	SALWA2EF3EA332508
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Autobiography
Model Year	2014
Color	Green
Mileage	222783 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Engine Condition		المحرك
01.A Visual Engine Condition	SIGN OF LEAK	حالة المحرك النظري
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OK	حالة الجير النظري
03 Tires and Rims Condition		الاطارات
03.A Rear Tyre	BOTH SIDE 2018 CRACKED	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2018 CRACKED	الاطار الامامي
04 Body		جسم المركبة
04.A Floor	UNDER FLOOR COVERED , CHECKED VISIBLE AREA OK	الارضية
04.B Fenders	PORTION REPAIRED, REPAINTED	مدكار
04.C Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
04.D Doors	PORTION REPAIRED, REPAINTED	أبواب
05 Chassis Condition		الشاصي

DEFECT	REMARKS	
05.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.