CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2949288
Transaction Date	05 Nov 2026, 10:52:25
Site Name	840 - Emirates Auctions
Transaction Number	92389597 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MNTBC2C99E*******
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2014
Color	Red
Mileage	177578 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY ORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.F Bonnet	REFITTED,HINCH REPAIRED.	غطاء المحرك
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS END DENT, REAR EXTENSION END DENT GETTING RUSTY	الشاسيه
03 Engine Condition		**المحرك**
03.A Mount	BUSHES CRACKED	كرسي
03.B Smoke	WHITE	دخان
03.C Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2021 EXPIRED DAMAGED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2021 EXPIRED DAMAGED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY WEAK .	دواسة الفرامل
07.B Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK ,MOUNT BUSHES CUT .	ممتص الصدمات
08.B Arms	BUSHES CUT	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
09.B AC Condition	NOT COOLING.	المكيف
09.C Power Window Switch And Glass	NOT WORKING PROPERLY .	مفتاح النافذه و الزجاج
09.D Dash Board	GLOVE BOX DAMAGED	لوحة القياده
09.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae