CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2915730
Transaction Date	27 Oct 2026, 15:59:14
Site Name	840 - Emirates Auctions
Transaction Number	70251618 (CC10013) (CC10019)



Vehicle Details

Chassis Number	1GNSKHKC9H*******
Specification	Imported
Make	Chevrolet
Model	Suburban
Model Year	2017
Color	Black
Mileage	69292 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR RUST PROOFED DIRTY	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Pillars	LEFT SIDE B/ PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Sign of front accident	FRONT BUMPER FRAME RADIATOR SUPPORT BULK HEAD INNER FENDER FRAME REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED BEND / DENT COMPLETELY THICK RUST PROOFED	الشاسيه
02.B Chassis Number	VIN CHECK ONLY DOOR POST STICKER	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED , HOUSING BOLT LOOSE , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخري
08 Lights		الاضاءة
08.A Head Light	LENS FADED	الاضاءة الرئيسية
08.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES MINOR DRY CRACK	ازرع
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY	اخري
10.B Mirror	BOTH SIDE FOLDING NOT WORKING	المرايا
10.C AC Condition	OK	المكيف
10.D Dash Board	LEATHER PORTION LOOSE MINOR WORN OUT	لوحة القياده
10.E Roof Ceiling	PORTION WORN OUT	بطانه السقف
10.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae