CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3032917
Transaction Date	25 Nov 2026, 13:32:37
Site Name	840 - Emirates Auctions
Transaction Number	31931700 (CC10009) (CC10019)

Vehicle Details

Chassis Number	SALVA2BG0H*******
Specification	GCC Specification
Make	Range Rover
Model	Evoque
Model Year	2017
Color	Black
Mileage	122613 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECKED	مدكار
01.B Paint	BODY PORTION,REPAINTED ,PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE REPAINTED ,PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION MINOR DENT FRONT CHASSIS COVERED	الارضية
01.F Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.G Bonnet	REPAINTED ,PORTION REPAIRED,REFITTED	غطاء المحرك
01.H Trunk	FIBER PAINT NOT CHECKED	صندوق
01.I Fuel Tank	SIGN OF FUEL WET	خزان الوقود
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS COVERED PORTION MNOR DENT/OK	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	MINOR OIL LEAK PARTS REFITTED, ABNORMAL NOISY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Interior Condition		الحاله الداخليه
06.A Other	INTERIOR MODIFIED & CENTER CONSOLE BOX LOCK DAMAGED	اخري
06.B AC Condition	OK	المكيف
06.C Dash Board	LEATHER PORTION REPAIRED	لوحة القياده
06.D Roof Ceiling	PORTION LOOSE	بطانه السقف
06.E Sun Visor	LEFT SIDE PORTION LOOSE	حاجب الشمس
06.F Door Panel	PORTION LOOSE	لوحة بطانة الباب

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae