CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934068
Transaction Date	03 Nov 2026, 17:00:10
Site Name	840 - Emirates Auctions
Transaction Number	84534484 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JN1FN61C4A*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2010
Color	Red
Mileage	239798 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	UNDER FLOOR PORTION DENT ,MUDDY.,	دعامية
01.E Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT ,REAR EXTENSION REPAIRED DENT ,GETTING RUSTY.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACKED PUNCTURE.,	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACKED PUNCTURE.	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED.	الاضاءة الرئيسية
06.B Tail Light	PORTION CRACKED.	الضوء الخلفي
06.C Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	SPONGY.	دواسة الفرامل
07.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	BUSHES CUT	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CUT	ربلة المقود
09.B Steering Box	OIL LEAK.	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
10.B Mirror	CENTER MIRROR MISSING.	المرايا
10.C AC Condition	NOT COOLING.	المكيف
10.D Dash Board	PORTION DAMAGED .	لوحة القياده
10.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.