



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	09 Oct 2021, 18:03:54
Transaction Number	48994958 (CC10006)	Queue Number	312309



Chassis Number	JTHBN36FX65029295
Engine Number	
Vehicle Class	Car
Manufacturer	Lexus
Model	LS 430
Model Year	2006
Color	White
Mileage	0 N/A

DEFECT	REMARKS	
01 Interior Condition		الاجزاء الداخلية
01.A AC Condition	OK	المكيف
01.B Other	ROOF CONSOLE BOX NOT CLOSIING	اخرى
01.C Mirror	OK	المرايا
02 Body		جسم المركبة
02.A Floor	NEED TO REMOVE FRONT BOTH SIDE FLOOR MATTING COVER & SEAT FOR RECHK	الارضية
02.B Fenders	REPAIRED & REPAINTED	مدكار
02.C Paint	BODY TOTALY REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
02.D Doors	REPAIRED & REPAINTED	أبواب
02.E Rusty	UNDER FLOOR FULLY RUST PROOFED	صدأ
02.F Pillars	NEED TO REMOVE FRONT BOTH SIDE INNER PILLAR, ROCKER PANEL COVER FOR RECHK	القوائم
02.G Other	REAR BACK PANEL, SPARE WHEEL HOUSING, QUATER PANEL & FRONT FENDER FRAME, FIRE WALL AREA, BUMPER FRAME, BULKHEAD, RADITOR SUPPORT REPAIRED	اخرى
02.H Roof	REPAIRED & REPAINTED	السقف
02.I Bumper	REPAIRED & REPAINTED	دعامة
02.J Bonnet	REPAIRED & REPAINTED	غطاء المحرك
03 Transmission Condition		الجير
03.A Gear Box	TRANSMISSION SHIFT LOCK BOTTON COVER MISSING	الجير

DEFECT	REMARKS	
04 Steering Condition		المقود
04.A Other	STEERING WHEEL WORNOUT	اخرى
05 Chassis Condition		الشاسي
05.A Chassis	OK	الشاسيه
05.B Chassis Extension	REAR BOTH SIDE REPAIRED	تمديدات الشاسي
06 Engine Condition		المحرك
06.A Other	OK	اخرى
07 Lights		الاضاءة
07.A Head Light	OK	الاضاءة الرئيسية
08 Wipers and Arms		المساحات
08.A Other	WORN OUT	اخرى
09 Brake Condition		الفرامل
09.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
10 Tires and Rims Condition		الاطارات
10.A Front Tyre	BOTH 2016 CRACKED	الاطار الامامي
10.B Rear Tyre	BOTH SIDE 2016 CRACKED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.