

Queue Number 2862690

Transaction Date 14 Oct 2026, 12:13:24

Site Name
840 - Emirates AuctionsTransaction Number
78531816 (CC10010) (CC10019)

Vehicle Details

Chassis Number JTDBW92358*****
Specification GCC Specification
Make Toyota
Model Yaris
Model Year 2008
Color White
Mileage N/A NA
Fuel Type Petrol
Transmission Type
No. Of Cylinders 4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY PORTION FADED .	الصبغ
01.B Rusty	BODY PORTION RUSTY MUDDY.	صدأ
01.C Floor	UNDER FLOOR CHASSIS ,SUSPENSION PARTS NOT CHECKED .	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED.	دعامية
01.E Windshield	FRONT CRACKED	زجاج
01.F Other	VISUAL CHECK	اخرى
01.G Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD ,FENDER FRAME REPAIRED.	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS NOT CHECKED .	الشاسيه
02.B Chassis Number	VIN CHECKED ONLY STICKER .	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
---------------------	-----------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED .	الحالة النظرية للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
07.B Tail Light	PORTION DAMAGED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك و طنايير الفرامل
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX COVER DAMAGED & INTERIOR PARTS GETTING RUSTY,SIGN OF WATER FLOODED	اخرى
09.B Mirror	LEFT SIDE DAMAGED	المرآيا
09.C AC Condition	NOT CHECKED	المكيف
09.D Dash Board	PORTION CRACKED DAMAGED	لوحة القيادة
09.E Odometer reading	NOT CHECKED	قراءة عداد المسافات
09.F Door Panel	PORTION CRACKED WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae