

Queue Number 2874387

Transaction Date 16 Oct 2026, 16:45:12

Site Name
840 - Emirates AuctionsTransaction Number
13009960 (CC10009) (CC10012)

Vehicle Details

Chassis Number	KNAMB8124G*****
Specification	GCC Specification
Make	Kia
Model	Carnival
Model Year	2016
Color	Blue
Mileage	118545 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , BODY RUSTY , PORTION FADED	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR COVERED MUDDY PORTION DENT	الارضية
01.E Bumper	MISALIGN , GRILL PORTION CRACK , COVER SKIRT MISSING	دعامية
01.F Trunk	NOT OPEN , LEFT SIDE SKIRT MELTED CRACKED	صندوق
01.G Door Handle &Lock	LOCK DOOR NOT WORKING , FRONT RIGHT SIDE HANDLE LOOSE	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION GETTING RUSTY,OK	الشاسيه
--------------	----------------------------------	---------

03 Engine Condition

المحرك

03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MUDDY OILY	الحالة النظرية للمحرك

04 Seats Condition

المقاعد

04.A Seat Condition	SEAT EXTRA COVER , PORTION CUT	حالة المقاعد
---------------------	--------------------------------	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED GETTING RUSTY MINOR JERKING	الحالة النظرية للجير
05.B Road Test	NOT CHEKCED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2022 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2022 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES , REAR LEFT HUB COVER MISSING	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	BOTH SIDE LENS FADED , RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE PORTION CRACK	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Hand Brake	NOT WORKING	فرامل اليد
09 Suspension System		ممتص الصدمات
09.A Arms	BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING RUSTY, (SIGN OF FLOODED) , CENTER CONSOLE BOX LOCK MISSING	اخرى
10.B AC Condition	LOW COOLING , GRILL PORTION CRACK , ADJUSTMENT MISSING	المكيف
10.C Sun Visor	COVER MISSING , LEFT SIDE BRACKET DAMAGED ,	حاجب الشمس
10.D Odometer reading	DISPLAY PANEL PORTION CRACK	قراءة عداد المسافات
10.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص. ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

