



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Sep 2022, 13:00:45
Transaction Number	66290509 (CC10006)	Queue Number	594502



Chassis Number	SALLMAME4BA339883
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Vogue
Model Year	2011
Color	Gold
Mileage	242094 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Other	ROOF, RAIL REPAINTED PORTION REPAIRED	اخرى
01.B Trunk	REFITTED ,PORTION REPAIRED REPAINTED ,AUTO LOCK NOT WORKING PROPERLY.	صندوق
01.C Paint	BODY REPAINTED , PORTION REPAIRED MINOR DENTS SCRATCHES	الصبغ
01.D Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Roof	REPAINTED	السقف
01.F Fenders	REAR BOTH SIDE PORTION REPAIRED, REPAINTED	مدكار
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Chassis Condition		الشاسيه
03.A Chassis	CHECKED,VISIBLE AREA OK.	الشاسيه
04 Interior Condition		الحاله الداخليه
04.A AC Condition	OK	المكيف
05 Transmission Condition		الجير

DEFECT	REMARKS	
05.A Road Test	NOT CHECK	فحص علي الطريق
05.B Visual Gear Box Condition	OIL LEAK & REFITTED	حالة الجير النظري
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE LIGHT BRACKET DAMAGED & LOOSE	الاضاءة الرئيسية
07 Engine Condition		المحرك
07.A Visual Engine Condition	OIL LEAK & REFITTED	حالة المحرك النظري
08 Steering Condition		المقود
08.A Axle	BOOT CUT	اكسلات
09 Seats Condition		المقاعد
09.A Seat Condition	DRIVER SEAT PORTION DAMAGED	حالة المقاعد
10 Suspension System		ممتص الصدمات
10.A Arms	LOWER ARM BUSH CRACKED	ازرع

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.