CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899677
Transaction Date	28 Oct 2026, 14:59:30
Site Name	840 - Emirates Auctions
Transaction Number	69237620 (CC10010) (CC10011)



Vehicle Details

Chassis Number	KMHDH4AE9C*******
Specification	Imported
Make	Hyundai
Model	Elantra
Model Year	2012
Color	Black
Mileage	N/A NA
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REAR LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT PORTION REPAIRED REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION GETTING FADED RUSTY	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED,RIGHT PORTION REPAIRED REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN SCRATCHES	دعامية
01.G Sign of side accident	QUARTER PANEL.BACK PANEL REPAIRED.	وجود مؤشر لحادث في الجانب
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2022 CRACK,RIGHT 2021 CRACK EXPIRED PUNCTURE	الاطار الامامي
06.B Rear Tyre	LEFT SIDE 2023 CRACK,RIGHT 2021 CRACK EXPIRED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Arms	BUSHES CRACKED .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX COVER LOCK NOT WORKING,INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT CHECK,SWITCH WORN OUT	المكيف
11.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae