





Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27093515	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2021 10:16:13	Plate Number	: 032158 EA
Queue Number	: 352082	Import Doc. Ref.	:
Chassis Number	: JN8FY1NY9KX032158	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks	
AUTOMATIC TEST:			
13 Brake System			الفرامل
13.04 - Brake Test	Passed		فحص الفرامل
14 Exhaust Gas Test			الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed		فحص الغاز العادم-الكربون
16 Side Slip Test			فحص ميزانية الاطارات
16.01 - Side Slip Test	Passed		فحص ميزانية الاطارات
VISUAL TEST:			
04 Tires Rims			الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		TIRES 2017	الاطارات الامامية
05 Body			الهيكل
05.03 - Doors		DOOR PILLARS & ROOF PANEL REPAIRED	الابواب
05.08 - Chassis (Frame)		REAR BOTH SIDE CHASSIS BULGED & FRONT RIGHT SIDE INNER DENT & FRONT LEFT SIDE END	الشاصية
05.09 - Front And Rear Windshields		FRONT REPLACED	الزجاج الامامي والخلفي
05.12 - Side Safety Frame		BULKHEAD /RADIATOR SUPPORT /FENDER FRAME REPAIRED	الواقيات الجانبية
06 General Items			الاشياء العامة
06.14 - Transmission Condition	OK		حالة ناقل الحركة
06.16 - Engine Condition, Smoke		ENGINE SOME PARTS RE-FITTED/ BLACK SMOKE	حالة المحرك - الدخان
07 Remarks			ملاحظات
07.02 - Chassis No.		VIN NUMBER REPUNCHED (JN8FY1NY9KX032158)	رقم الشاصي
07.04 - Others		17065 KM BONNET & FRONT RIGHT FENDER REPLACED	ملاحظات اخرى
09 Auction			الفحص الكامل
09.02 - Need Wheel Alignment			بحاجة الى ميزانية العجلات
09.14 - Sign Of Front Accident			أثر حادث في مقدمة المركبة
09.25 - Body Repainted			أثر صيغ في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 27093515	Plate Category	: PRIVATE
Transaction Date	: 16 JUN 2021 10:16:13	Plate Number	: 032158 EA
Queue Number	: 352082	Import Doc. Ref.	:
Chassis Number	: JN8FY1NY9KX032158	Manufacturer/Model	: NISSAN/PATROL
Engine Number	:	Model Year	: 2019
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: BLACK
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسئول عن العيوب الخفية

Test Certificate



Vehicle
Registration



✓ PASS

Export Certificate :	65141636
Chassis No :	JN8FY1NY9KX032158
Vehicle Make :	NISSAN
Vehicle Model :	PATROL
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Black
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	17067 Kms.
Origin :	Japan
Model Year :	2019
Gear Type :	--
Engine Size :	3500 CC
Engine No :	TB48 115076
Horse Power :	--
Axles No :	2
Cylinders :	6
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 2812 Kgs. 3500 Kgs.

Certificate Number :	5-TAS-2021-14431118
Inspection Date :	17-06-2021
Certificate Print Date :	17-06-2021
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Emirates Auction
Total Time Taken :	14 min 13 sec
Appointment Ref Number :	--
Start Time :	17:17
End Time :	17:31
Lane :	01
Token No. :	16
Attempt :	1
Prints No :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate in 12 Months)



585 KM

Distance per
year



61 L

Fuel consumed
per year



99 AED

Fuel cost per
year



0.2 ton

Carbon footprint
per year

Parameter Readings

Service brake imbalance on
front axle
27 %

Service brake imbalance on
rear axle
10 %

Parking brake imbalance
between LHS and RHS
15 %

Vehicle on Petrol CO
Reading
3.86 %

Vehicle on Petrol HC Reading

181 PPM VOL

Inspection Findings

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3500	4800	

Inspection Remarks:

BOTH SIDE DOOR PILLAR REPAIRED /VIN NUMBER RE PUNCHED HAVE COMPANY LETTER OLD, REAR BOTH SIDE CHASSIS MINOR BULGE NEAR COIL SPRING AREA, CHASSIS & FLOOR THICK RUST PROOFED

Payment Details

Inspection Performed by
59460

Parking Slot No
--

Payment Method
VTP Credit Account

Service Name
Registration Test

Transaction Number
14431118

Attempt
1

Service Fees
AED 170 Collected on 17/06/2021

Received by
Raul Canceran Galang

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

