CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2944997
Transaction Date	09 Nov 2026, 13:04:16
Site Name	840 - Emirates Auctions
Transaction Number	62036877 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JM7GJ4S7XG*******
Specification	GCC Specification
Make	Mazda
Model	6
Model Year	2016
Color	White
Mileage	350015 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT BOTH SIDE ,REAR RIGHT SIDE REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	REAR RIGHT SIDE REPAIRED REPAINTED .	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED REFITTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA /OK.	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY PORTION LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED,	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED,	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED.	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK	ممتص الصدمات
09.B Arms	BUSHES CRACKED.	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CRACKED	ربلة المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
11.B AC Condition	NOT CHECKED.	المكيف
11.C Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
11.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات
11.F Engine Start Button	PORTION CUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.