CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2891201
Transaction Date	21 Oct 2026, 16:44:38
Site Name	840 - Emirates Auctions
Transaction Number	51006353 (CC10013) (CC10011)



Vehicle Details

Chassis Number	JN8AY2NY9F*******
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2015
Color	White
Mileage	115933 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION RUSTY(BODY SHAPE CHANGE OLD TO NEW MODEL)	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR BODY PORTION DIRTY GETTING RUSTY	الارضية
01.E Bumper	MISALIGN,PORTION CRACKED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	AUTO NOT WORKING,REFITTED NOISY	صندوق
01.H Sign of front accident	FRONT BUMPER FRAEM RADIATOR SUPPORT BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS FRAME RUST PROOFED PORTION RUSTY BULGED	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	MINOR WHITE	دخان
03.B Other	INNER ELECTRIC WIREING WORN OUT UNSAFE	اخري
03.C Engine Visual Condition	OIL PAN DENT , OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	COVER PORTION DAMAGED WORN OUT,DRIVER SEAT LOOSE	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	MINOR JERKING ,REFITTED , PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025 GETTING WORN OUT	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Spare Tire &Tools	TOOLS MISSING	الاطار الاحتياطي و العدة
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخري
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08.B Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
09 Suspension System		ممتص الصدمات
09.A Arms	ARM BUSHES CRACK	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Tie Rod End	BOOT CUT	مؤخرة الرودات
11 Interior Condition		الحاله الداخليه
11.A Other	COOL BOX NOT WORKING & INTERIOR MODIFIED PARTS REFITTED GETTING RUSTY SIGN OF FLOODED	اخري
11.B Mirror	BOTH SIDE AUTO FOLDING,ADJUSTMENT NOT WORKING LOOSE & CENTER VIEW MIRROR LOOSE BACK COVER PART MISSING	المرايا
11.C AC Condition	OK	المكيف
11.D Power Window Switch And Glass	SWITCH PORTION WORN OUT	مفتاح النافذه و الزجاج
11.E Dash Board	LEATHER PORTION LOOSE	لوحة القياده
11.F Roof Ceiling	PORTION LOOSE	بطانه السقف
11.G Sun Visor	LEFT SIDE BRACKET MISSING,MIRROR COVER LOOSE	حاجب الشمس
11.H Door Panel	PORTION DAMAGED	لوحة بطانة الباب
11.I Gear Shifting Lever	KNOB WORN OUT / PUSH BUTTON STUCK	ذراع نقل السرعات
11.J Engine Start Button	WORN OUT	زر تشغيل المحرك
12 Battery Condition		حالة البطارية
12.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae