

Queue Number	2784578	Transaction Date	22 Sep 2026, 12:58:38
Site Name	840 - Emirates Auctions	Transaction Number	59546947 (CC10010) (CC10011)



Vehicle Details

Chassis Number	MMDAFT6J3N*****
Specification	GCC Specification
Make	Mitsubishi
Model	Attrage
Model Year	2022
Color	Grey
Mileage	70826 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	3

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة	
01.A Fenders	FRONT RIGHT SIDE REPAIRED REPAINTED,REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR RIGHT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Bumper	MISALIGN,PORION DAMAGED	دعامية
01.F Trunk	REPAINTED PORTION REPAIRED,REFITTED	صندوق
01.G Sign of front accident	FRONT RIGHT SIDE BULKHEAD ,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.H Sign of back accident	REAR RIGHT SIDE BUMPER FRAME ,CRASH BOX KINK ,DENT,BACK PANEL REPAIRED DETACHED ,.	وجود مؤشر لحادث في الخلف

02 Chassis Condition		الشاسي
02.A Chassis	FRONT RIGHT SIDE CHASSIS END OUTER SKIRT REAR RIGHT SIDE EXTENSION END MINOR DENT .	الشاسيه

03 Engine Condition		المحرك
03.A Engine Visual Condition	VISUAL CHECK OK.	الحالة النظرية للمحرك

04 Transmission Condition		الجير
04.A Gear Box Visual Condition	MINOR JERKING.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص على الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	RIGHT SIDE DAMAGED	الاضاءة الرئيسية
07 Interior Condition		الحالة الداخليه
07.A Other	CENTER USB PANEL PART MISSING	اخرى
07.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae