

Queue Number	2408775	Transaction Date	22 May 2026, 14:32:00
Site Name	840 - Emirates Auctions	Transaction Number	42568942 (CC10006) (CC10006)



Vehicle Details

Chassis Number	JN6BE6AS9M*****
Specification	GCC Specification
Make	Nissan
Model	Urvan
Model Year	2021
Color	White
Mileage	209244 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		
		جسم المركبة
01.A Paint	PORTION STICKER, PORTION RUSTY, PORTION REPAIRED, PORTION FADED , DENTS, SCRATCHES ON BODY	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	BOTH SIDE RUNNING BOARD PORTION DENT, GETTING RUSTY	الارضية
01.D Sign of side accident		وجود مؤشر لحادث في الجانب
02 Chassis Condition		
		الشاسي
02.A Chassis	OK	الشاسيه
03 Engine Condition		
		المحرك
03.A Mount	BUSHES CUT, MOUNT GETTING RUSTY	كرسي
03.B Engine Visual Condition	OIL WET, SHAKING,PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		
		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		
		الجير
05.A Gear Box Visual Condition	REFITTED, OIL WET, PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Gear Box Mount	BUSH CUT	كرسي الجير
06 Tires and Rims Condition		
		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2022/2023 WORN OUT, DRY CRACKED	الاطار الامامي
06.B Rear Tyre	BOTHSIDE 2021/2022 DRY CRACKED, WORN OUT	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS SLIGHTLY FADED, PORTION CRACKED	الاضاءة الرئيسية
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	WEAK	ممتص الصدمات
08.B Leaf Spring	BUSHES CUT	
08.C Arms	LOWER ARM BUSHES CRACKED	ازرع
08.D Ball Joint	BOOT CUT	مفصل كروي
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT COOLING	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae