

Queue Number

2899772

Transaction Date

29 Oct 2026, 13:22:25

Site Name

840 - Emirates Auctions

Transaction Number

82830061 (CC10006) (CC10006)



Vehicle Details

Chassis Number

VF1HSRMX3P*****

Specification

GCC Specification

Make

Renault

Model

Duster

Model Year

2023

Color

Blue

Mileage

76292 Km

Fuel Type

Petrol

Transmission Type

No. Of Cylinders

4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY MINOR SCRATCHES DENTS	الصيغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR THICK RUST PROOFED PORTION DENTS, MUDDY	الارضية
01.D Bumper	TOW HOOK COVER MISSING	دعامية

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED , CHECK VISIBLE AREA ONLY / OK	الشاسية
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START , ALL SYSTEM NOT CHECK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	NOT CHECKED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

05 Tires and Rims Condition

الاطارات

05.A Front Tyre	BOTH SIDE 2022	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2022	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القيادة
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae