

Queue Number

2827629

Transaction Date

03 Oct 2026, 13:00:27

Site Name

840 - Emirates Auctions

Transaction Number

73262105 (CC10021) (CC10021)



## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | WVWFK2AU1G*****   |
| Specification     | GCC Specification |
| Make              | Volkswagen        |
| Model             | GTI               |
| Model Year        | 2016              |
| Color             | Red               |
| Mileage           | 298542 Km         |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 4                 |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|              |                                                                |       |
|--------------|----------------------------------------------------------------|-------|
| 01.A Fenders | REAR RIGHT SIDE REPAINTED,PORION REPAIRED,FRONT RIGHT REFITTED | مدكار |
| 01.B Paint   | BODY PORION REPAINTED PORION REPAIRED MINOR DENT SCRATCHES     | الصبغ |
| 01.C Doors   | BOTH RIGHT SIDE REPAINTED,PORION REPAIRED                      | أبواب |
| 01.D Rusty   | UNDER BODY PARTS, SUSPENTION GETTING RUSTY                     | صدأ   |

## 02 Chassis Condition

## الشاسي

|              |                                                     |         |
|--------------|-----------------------------------------------------|---------|
| 02.A Chassis | CHASSIS COVERD,MUDDY,CHECKED VISIBLE AREA ONLY / OK | الشاسيه |
|--------------|-----------------------------------------------------|---------|

## 03 Engine Condition

## المحرك

|                              |                                                   |                       |
|------------------------------|---------------------------------------------------|-----------------------|
| 03.A Engine Visual Condition | PARTS REFITTED,MINOR OIL LEAK,PARTS GETTING RUSTY | الحالة النظرية للمحرك |
|------------------------------|---------------------------------------------------|-----------------------|

## 04 Transmission Condition

## الجير

|                                |                |                      |
|--------------------------------|----------------|----------------------|
| 04.A Gear Box Visual Condition | PARTS REFITTED | الحالة النظرية للجير |
| 04.B Road Test                 | NOT CHECK      | فحص علي الطريق       |

## 05 Tires and Rims Condition

## الاطارات

|                     |                                |                |
|---------------------|--------------------------------|----------------|
| 05.A Front Tyre     | BOTH SIDE 2024                 | الاطار الامامي |
| 05.B Rear Tyre      | BOTH SIDE 2024 LEFT SIDE CRACK | الاطار الخلفي  |
| 05.C Rims Condition | MINOR DENT SCRATCHES           | حالة الجنوط    |

| Condition                               | Remarks                      | الحالة                     |
|-----------------------------------------|------------------------------|----------------------------|
| <b>06 Brake Condition</b>               |                              | <b>الفرامل</b>             |
| 06.A Disc&Drum                          | RUSTY                        | دسك و طناوير الفرامل       |
| <b>07 Suspension System</b>             |                              | <b>ممتص الصدمات</b>        |
| 07.A Arms                               | BUSHES CRACK                 | ازرع                       |
| <b>08 Steering Condition</b>            |                              | <b>المقود</b>              |
| 08.A Tie Rod End                        | BOOT CUT                     | مؤخرة الرودادات            |
| <b>09 Interior Condition</b>            |                              | <b>الحالة الداخلية</b>     |
| 09.A Other                              | INTERIOR PARTS GETTING RUSTY | اخرى                       |
| 09.B AC Condition                       | NOT COOLING                  | المكيف                     |
| 09.C Steering Wheel and control buttons | WORN OUT                     | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

لشكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)