CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899785
Transaction Date	26 Oct 2026, 11:16:43
Site Name	840 - Emirates Auctions
Transaction Number	15541393 (CC10006) (CC10011)



Vehicle Details

Chassis Number	LJNTFU2K7F*******
Specification	GCC Specification
Make	ZNA
Model	RICH
Model Year	2015
Color	White
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES ,PORTION RUSTY FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR DENT.,	الارضية
01.D Bumper	MISALIGN PORTION DAMAGED	دعامية
01.E Trunk	TAILGATE MISALIGN NOT CLOSE PROPERLY LOCK HANDLE DAMAGED	صندوق
01.F Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		الشاصي
02.A Chassis	BOTH SIDE CHASSIS REPAIRED PORTION DENT GETTING RUSTY. MUDDY .	الشاسيه
02.B Chassis Number	VIN AREA RUSTY.	رقم القاعدة
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	LEFT SIDE 2020 EXPIRED DAMAGED,RIGHT 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2020 EXPIRED DAMAGED	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED,ALL LIGHT NOT CHECKED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE FADED	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Leaf Spring	BUSHES CUT.	
09.C Arms	BUSHES CUT .	ازرع
09.D Stabilizer Bar And Link Rod	BUSHES CUT	عمود التوازن و مثبت عمود التوازن
10 Steering Condition		المقود
10.A Steering Boot	CUT	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	CENTER CONSOLE BOX,PANEL LOOSE LOCK DAMAGED	اخري
11.B Mirror	LEFT SIDE BRACKET DAMAGED	المرايا
11.C AC Condition	NOT CHECK	المكيف
11.D Roof Light	MISSING	أنارة السقف
11.E Dash Board	PORTION CRACKED WORN OUT	لوحة القياده
11.F Roof Ceiling	DIRTY	بطانه السقف
11.G Odometer reading	NOT CHECK	قراءة عداد المسافات
11.H Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
11.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.J Gear Shifting Lever	KNOB WORN OUT,DUST COVER LOOSE	ذراع نقل السرعات
12 Battery Condition		حالة البطارية
12.A Battery Condition	MISSING	حالة البطارية

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**