

Queue Number

2797763

Transaction Date

25 Sep 2026, 16:31:15

Site Name

840 - Emirates Auctions

Transaction Number

82826079 (CC10010) (CC10011)



Vehicle Details

Chassis Number	4JGBB7HBXA*****
Specification	Imported
Make	Mercedes
Model	ML 63
Model Year	2010
Color	Black
Mileage	192236 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , REAR RIGHT SIDE REPAIRED REPAINTED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR CHASSIS COVERED, CHECKED ONLY VISIBLE AREA .	الارضية
01.F Bumper	MISALIGN,TOWING HOOK COVER MISSING	دعامية
01.G Bonnet	MISALIGN , UPPER GRILL PORTION CRACK	غطاء المحرك
01.H Pillars	RIGHT SIDE C/PILLAR ROCKER PANEL REPAIRED	القوائم
01.I Trunk	REFITTED , STAY SHOCK MISSING , AUTOMATIC NOT WORKING , LAUGGAGE SHADE , BRACKET MISSING	صندوق
01.J Door Handle & Lock	DOORS OUTER HANDLE LOCK SENSOR SWICTH DAMAGE	مقابض الأبواب والأقفال

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED PORTION OILY MUDDY ,CHECKED VISIBLE AREA OK.	الشاسيه
02.B Other	STEAM WASH CHASSIS FOR INSPECTION .	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS REFITTED OIL LEAK ,COMPONENT PARTS GETTING RUSTY AIR INTAKE PIPE MISSING.SHAKING. OIL STICK DAMAGED.	الحالة النظرية للمحرك
------------------------------	---	-----------------------

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION DAMAGED WORN OUT,FRONT RIGHT SEAT SIDE PANEL COVER DAMAGE	حالة المقاعد
05 Exhaust System		نظام العادم
05.A Other	NOISY.	اخرى
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	PARTS REFITTED OIL LEAK GET JERKING.	الحالة النظرية للجير
06.B Road Test	NOT CHECKED .	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2024 CRACK GETTING WORN OUT	الاطار الامامي
07.B Rear Tyre	RIGHT SIDE 2023 , LEFT SIDE 2024 CRACK GETTING WORN OUT	الاطار الخلفي
07.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
08 Wipers and Arms		المساحات
08.A Other	TANK CAP MISSING.	اخرى
08.B Wiper Arm &Blade	WATER TANK COVER MISSING	ازرع المساحات والشفرات
09 Lights		الاضاءة
09.A Head Light	BOTH SIDE DAMAGED REPAIRED,LENS GETTING FADED,RIGHT SIDE SIGN OF CRACK	الاضاءة الرئيسية
09.B Warning Light	WARNING LIGHT , MESSAGE ON DISPLAY	ضوء تحذير
09.C Fog light	NOT WORKING	كشف الضباب
10 Brake Condition		الفرامل
10.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
10.B Hand Brake	RELEASE HANDLE DAMAGE/FIXED BY GLUE.	فرامل اليد
11 Steering Condition		المقود
11.A Steering Boot	CUT .	ربلة المقود
11.B Steering Box	OIL LEAK .	جهاز المقود
12 Interior Condition		الحالة الداخلية
12.A Other	CENTER CONSOLE BOX COVER LOCK DAMAGE WORN OUT,CIGARETTE LIGHTER ASHTRAY BOX COVER MISSING,INTERIOR PARTS GETTING RUSTY,SIGN OF FLOODED.	اخرى
12.B Mirror	LEFT SIDE LOOSE AUTO FOLDING NOT WORKING INDICATOR LIGHT COVER MISSING,RIGHT SIDE INDICATOR LIGHT COVER PORTION CRACK,CENTER MIRROR LOOSE BACK COVER PART MISSING	المرآيا
12.C AC Condition	OK,GRILL PORTION DAMAGED LOOSE,GRILL ADJUSTER MISSING	المكيف
12.D Roof Light	FRONT PANEL LOOSE	أنارة السقف
12.E Power Window Switch And Glass	REAR RIGHT SIDE SWICTH NOT WORKING PROPERLY	مفتاح النافذه و الزجاج
12.F Audio	LCD SCREEN FADED PORTION DAMAGED	صوتيات
12.G Dash Board	LEATHER REFITTED PORTION LOOSE	لوحة القيادة
12.H Sun Visor	LEFT SIDE LOOSE	حاجب الشمس

Condition	Remarks	الحالة
12.I Odometer reading	CLUSTER DISPLAY GETTING FADED	قراءة عداد المسافات
12.J Door Panel	LEATHER REFITTED PORTION LOOSE , CRACK	لوحة بطانة الباب
12.K Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
12.L Sunroof	NOT WORKING PROPERLY	فتحت سقف
12.M Engine Start Button	REMOTE,START BUTTON PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae