



## TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **17 May 2023, 17:02:18**  
 Transaction Number **70017680 (CC10010)** Queue Number **716340**



Chassis Number **KL1PJ5C56GK304651**  
 Engine Number  
 Vehicle Class **Car**  
 Manufacturer **Chevrolet**  
 Model **Cruze LS**  
 Model Year **2016**  
 Color **White**  
 Mileage **001 Km**  
 Fuel Type **Petrol**  
 No. Of Cylinders **4**  
 Specification **GCC Specification**

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2018 EXPIRED ,CRACKED .	الاطار الخلفي
<b>02 Interior Condition</b>		<b>الحالة الداخلية</b>
02.A Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
02.B AC Condition	NOT CHECKED.	المكيف
02.C Other	INTERIOR DIRTY, MUDDY. .	اخرى
02.D Odometer reading	NOT CHECKED.	قراءة عداد المسافات
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Sign of side accident		وجود مؤشر لحادث في الجانب
03.B Other	BACK PANEL QUARTER PANEL REPAIRED.	اخرى
03.C Trunk	NOT OPEN . PORTION REPAINTED.	صندوق
03.D Doors	RIGHT SIDE REPAINTED ,PORTION REPAIRED.	أبواب
03.E Fenders	RIGHT SIDE FRONT REPAIRED ,REPAINTED ,REAR RIGHT SIDE QUARTER PANEL ,WHEEL ARCH REPAIRED ,REPAINTED.	مدكار
03.F Floor	PORTION DENT .	الارضية

DEFECT	REMARKS	
03.G Sign of back accident		وجود مؤشر لحادث في الخلف
03.H Paint	BODY PORTION REPAIRED ,PORTION REPAINTED ,DENTS SCRATCHES .	الصبغ
03.I Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY	صدأ
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A Visual Gear Box Condition	NOT CHECKED .	حالة الجير النظري
04.B Road Test	NOT CHECKED .	فحص علي الطريق
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	CHECKED ONLY VISIBLE AREA OK.	الشاسيه
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Head Light	LENS FADED ,ALL LIGHTS NOT CHECKED .,	الاضاءة الرئيسية
<b>07 Suspension System</b>		<b>ممتص الصدمات</b>
07.A Shock Absorber	WEAK & MINOR OIL LEAK .	ممتص الصدمات
07.B Arms	LOWER ARM BUSHES CRACKED.	ازرع
<b>08 Engine Condition</b>		<b>المحرك</b>
08.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING.	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.