



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>27 Sep 2022, 13:11:52</b>
Transaction Number	<b>68099615 (CC10006)</b>	Queue Number	<b>597021</b>



Chassis Number	<b>SALEA7BE2N2101727</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Land Rover</b>
Model	<b>Defender</b>
Model Year	<b>2022</b>
Color	<b>White</b>
Mileage	<b>10828 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>8</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Tires and Rims Condition</b>		<b>الاطارات</b>
01.A Front Tyre	BOTH SIDE 2021.	الاطار الامامي
01.B Rear Tyre	BOTH SIDE 2021.	الاطار الخلفي
<b>02 Transmission Condition</b>		<b>الجير</b>
02.A Visual Gear Box Condition	OK	حالة الجير النظرى
02.B Road Test	NOT CHECKED.	فحص علي الطريق
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Floor	UNDER FLOOR COMPLETE COVERED ,CHECKED ONLY VISIBLE AREA.	الارضية
03.B Paint	MINOR SCRATCHES.	الصبغ
03.C Windshield	DARK TINTED.	زجاج
<b>04 Engine Condition</b>		<b>المحرك</b>
04.A Visual Engine Condition	OK	حالة المحرك النظرى
<b>05 Chassis Condition</b>		<b>الشاسي</b>
05.A Chassis	CHECKED,VISIBLE AREA OK.	الشاسيه

## DEFECT

## REMARKS

06 Interior Condition

الحاله الداخليه

06.A AC Condition

OK

المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.