

## **TEST CERTIFICATE**

أبواب

الارضية

اخری

الجير

وجود مؤشر لحادث في الخلف

Site Number
Transaction Number

03.E Doors

03.G Floor

03.H Other

03.F Sign of back accident

**04 Transmission Condition** 

840-Emirates Auctions 49022330 (CC10006) Transaction Date

17 May 2022, 16:37:34

Queue Number 312309

Chassis Number

3PCAJ5M39KF111914

Engine Number

Vehicle Class Car

Manufacturer Infiniti

Model QX50

Model Year 2019

Color Blue

Mileage 46640 Km

Fuel Type Petrol

No. Of Cylinders

Specification GCC Specification



## **01 Interior Condition** الحاله الداخليه 01.A AC Condition OK المكيف **02 Tires and Rims Condition** الاطارات **BOTH SIDE 2017 EXPIRED CRACKED** 02.A Front Tyre الاطار الامامي 02.B Rear Tyre **BOTH SIDE 2017 EXPIRED CRACKED** الاطار الخلفى 03 Body جسم المركبة RIGHT SIDE FRONT REAR REPAINTED, PORTION REPAIRED 03.A Fenders مدكار 03.B Trunk REPAIRED REPAINTED صندوق 03.C Bonnet REFITTED غطاء المحرك 03.D Paint BODY REPAINTED, PORTION REPAIRED & DENTS, الصبغ **SCRATCHES ON BODY**

FRONT RIGHT SIDE DOOR REPAINTED

UNDER FLOOR COVERED CHECKED VISIBLE AREA

**BACK PANEL REPAIRED** 

| DEFECT                            | REMARKS                  |                    |
|-----------------------------------|--------------------------|--------------------|
| 04.B Visual Gear Box<br>Condition | OK                       | حالة الجير النظرى  |
| 05 Engine Condition               |                          | المحرك             |
| 05.A Visual Engine Condition      | OK                       | حالة المحرك النظرى |
| 06 Chassis Condition              |                          | الشاصي             |
| 06.A Chassis                      | CHECKED VISIBLE AREA OK  | الشاسيه            |
| 07 Suspension System              |                          | ممتص الصدمات       |
| 07.A Arms                         | LOWER ARM BUSHES CRACKED | ازرع               |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.