



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Sep 2021, 18:03:50
Transaction Number	99998280 (CC10006)	Queue Number	312309



Chassis Number	5N1AA0NC8BN617040
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Armada
Model Year	2011
Color	White
Mileage	293685

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE & REAR RIGHT SIDE REPAINTED	مدكار
01.B Paint	PORTION REPAIRED, REPAINTED & DENTS, SCRATCHES ON BODY	الصبغ
01.C Doors	RIGHT SIDE BOTH, REAR LEFT SIDE REPAIRED, REPAINTED & FROBNT LEFT SIDE REPAINTED	أبواب
01.D Bumper	REPAINTED	دعامية
01.E Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
02 Chassis Condition		الشاصي
02.A Chassis	OK	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL LEAK & REFFITED	اخرى
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Transmission Condition		الجير
05.A Gear Box	OK	الجير
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018/2020	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي

DEFECT	REMARKS	
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Brake Condition		الفرامل
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
09 Suspension System		ممتص الصدمات
09.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES DRY CRACKED	ازرع
10 Interior Condition		الاجزاء الداخلية
10.A Other	SLYDING ROOF NOT WORKING PROPERLY	اخرى
10.B Mirror	OK	المرايا
10.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.