



## TEST CERTIFICATE

|                    |                              |                  |                              |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number        | <b>840-Emirates Auctions</b> | Transaction Date | <b>23 Nov 2022, 13:27:54</b> |
| Transaction Number | <b>25306131 (CC10009)</b>    | Queue Number     | <b>628285</b>                |



|                  |                          |
|------------------|--------------------------|
| Chassis Number   | <b>WDDBF4EB2DJ069125</b> |
| Engine Number    |                          |
| Vehicle Class    | <b>Car</b>               |
| Manufacturer     | <b>Mercedes</b>          |
| Model            | <b>A 250</b>             |
| Model Year       | <b>2013</b>              |
| Color            | <b>White</b>             |
| Mileage          | <b>333472 Km</b>         |
| Fuel Type        | <b>Petrol</b>            |
| No. Of Cylinders | <b>4</b>                 |
| Specification    | <b>GCC Specification</b> |

| DEFECT                           | REMARKS   |                        |
|----------------------------------|---|------------------------|
| <b>01 Transmission Condition</b> |   | <b>الجير</b>           |
| 01.A Road Test                   | NOT CHECK   | فحص علي الطريق         |
| 01.B Visual Gear Box Condition   | JERKING   | حالة الجير النظري      |
| 01.C Gear Box Mount              | MOUNT RUBBER CRACKED  | كرسي الجير             |
| <b>02 Body</b>                   |   | <b>جسم المركبة</b>     |
| 02.A Floor                       | UNDER FLOOR FENDER CHASSIS FULLY COVERED<br>CHECKED VISIBLE AREA ONLY | الارضية                |
| 02.B Paint                       | BODY PORTION REPAIRED , REPAINTED & MINOR DENT<br>,SCRATCHES,         | الصبغ                  |
| 02.C Fenders                     | FRONT LEFT SIDE REFITTED  | مدكار                  |
| <b>03 Chassis Condition</b>      |   | <b>الشاسي</b>          |
| 03.A Chassis                     | CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK                          | الشاسيه                |
| <b>04 Suspension System</b>      |   | <b>ممتص الصدمات</b>    |
| 04.A Arms                        | LOWER ARM BUSH CRACKED  | ازرع                   |
| 04.B Ball Joint                  | BOOT CUT  | مفصل كروي              |
| <b>05 Interior Condition</b>     |   | <b>الحاله الداخليه</b> |

| DEFECT                                  | REMARKS                        |                            |
|---|--------------------------------|----------------------------|
| 05.A AC Condition                       | LOW COOLING                    | المكيف                     |
| 05.B Steering Wheel and control buttons | WORN OUT                       | عجلة القيادة وازرار التحكم |
| <b>06 Steering Condition</b>            |                                | <b>المقود</b>              |
| 06.A Tie Rod End                        | BOOT CUT                       | مؤخرة الرودادات            |
| <b>07 Engine Condition</b>              |                                | <b>المحرك</b>              |
| 07.A Visual Engine Condition            | MINOR OIL LEAK, ABNORMAL NOISY | حالة المحرك النظري         |
| <b>08 Tires and Rims Condition</b>      |                                | <b>الاطارات</b>            |
| 08.A Rear Tyre                          | BOTH SIDE 2021                 | الاطار الخلفي              |
| 08.B Front Tyre                         | BOTH SIDE 2021                 | الاطار الامامي             |
| <b>09 Lights</b>                        |                                | <b>الاضاءة</b>             |
| 09.A Head Light                         | LENS FADED                     | الاضاءة الرئيسية           |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.