CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2906057
Transaction Date	28 Oct 2026, 10:11:33
Site Name	840 - Emirates Auctions
Transaction Number	23920329 (CC10026) (CC10021)



Vehicle Details

Chassis Number	4P3SRDJ1AB*******
Specification	GCC Specification
Make	Mitsubishi
Model	Galant
Model Year	2011
Color	Red
Mileage	595532 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY , SIGN OF FLOODED	صدأ
01.C Floor	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	الارضية
01.D Bumper	MISALIGN , PORTION DAMAGE , GRILL MISSING	دعامية
01.E Door Handle &Lock	FRONT RIGHT SIDE OUTER DOOR HANDLE DAMAGE	مقابض الأبواب والأقفال
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS MUDDY , OILY , PORTION DENT	الشاسيه
03 Engine Condition		المحرك
03.A Other	OIL PAN DENT	اخري
03.B Engine Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED PARTS GETTING RUSTY , MINOR OIL LEAK , MINOR JERKING	الحالة النظريه للجير
06 Tires and Rims Condition		الاطارات

Condition	Remarks	الحالة
06.A Front Tyre	BOTH SIDE 2024 CRACK	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACK	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS GETTING RUSTY	اخري
08.B Mirror	CENTER VIEW MIRROR FADED	المرايا
08.C AC Condition	OK	المكيف
08.D Roof Light	RIGHT SIDE DAMAGE	أنارة السقف
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae