CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2981807
Transaction Date	13 Nov 2026, 16:28:07
Site Name	840 - Emirates Auctions
Transaction Number	55123517 (CC10026) (CC10026)



Vehicle Details

Chassis Number	3N1AB8DV4L*******
Specification	Imported
Make	Nissan
Model	Altima
Model Year	2020
Color	Black
Mileage	119386 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPINTED PORTION REPAIRED , DENT SCRATCHES , PORTION RUSTY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.F Pillars	RIGHT SIDE A/B PILLAR ROCKER PANEL REPAIRED	القوائم
01.G Vehicle Model	SENTRA	طراز المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVER , CHECK VISIBLE AREA ONLY / OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي

Condition	Remarks	الحالة
05.B Rear Tyre	BOTH SIDE 2021 CRACK EXPIRED	الاطار الخلفي
05.C Rims Condition	DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LENS PORTION SCRATCHES	الاضاءة الرئيسية
06.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك وطنابير الفرامل
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX PORTION WORN OUT , INTERIOR PARTS GETTINGRUSTY , SIGN OF FLOODED	اخري
08.B AC Condition	OK	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.F Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae