



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>30 Aug 2021, 17:11:25</b>
Transaction Number	<b>29305021 (CC10007)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WDB4634117114144</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Mercedes</b>
Model	<b>G 500</b>
Model Year	<b>1999</b>
Color	<b>Blue</b>
Mileage	<b>163489</b>

DEFECT	REMARKS	
<b>01 Body</b>		<b>جسم المركبة</b>
01.A Fenders	PORTION REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS, CHASSIS FRAME GETTING RUSTY	صدأ
01.E Bumper	REPAINTED & MODIFIED	دعامية
01.F Roof	REPAINTED & SLYDING ROOF NOT WORKING	السقف
01.G Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.H Other	FRONT BUMPER FRAME, RADITOR SUPPORT, BULK HEAD, BODY MOUNT , CROSSMEMBER REPAIRED OLD	اخرى
01.I Pillars	ALL GETTING RUSTY	القوائم
<b>02 Chassis Condition</b>		<b>الشاسي</b>
02.A Chassis	CHASSIS FRAME RUSTY	الشاسيه
02.B Other	VIN NUMBER AREA RUSTY & STICKER ON LEFT SIDE DOOR MISSING	اخرى
<b>03 Engine Condition</b>		<b>المحرك</b>
03.A Other	OIL LEAK	اخرى
03.B Mount	BUSHES CRACKED	كرسي
<b>04 Seats Condition</b>		<b>المقاعد</b>

DEFECT	REMARKS	
04.A Other	OK	اخرى
<b>05 Exhaust System</b>		<b>نظام العادم</b>
05.A Modification	MODIFIED & NOISY	تعديلات
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Gear Box	OIL LEAK	الجير
06.B Propeller Shaft	POPELLAR SHAFT RUBBER CRACKED	ناقل الحركة
<b>07 Wipers and Arms</b>		<b>المساحات</b>
07.A Other	WORN OUT	اخرى
<b>08 Brake Condition</b>		<b>الفرامل</b>
08.A Caliber Brake	GETTING RUSTY	جهاز الفرامل
<b>09 Tires and Rims Condition</b>		<b>الاطارات</b>
09.A Front Tyre	BOTH SIDE 2017/2019 CRACKED & EXPIRED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017/ 2015 EXPIRED & CRACKED	الاطار الخلفي
<b>10 Interior Condition</b>		<b>الاجزاء الداخلية</b>
10.A Other	OK	اخرى
10.B Mirror	AUTO NOT WORKING	المرابا
10.C AC Condition	A/C NOT COOLING	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

# Test Certificate



Vehicle  
Registration



X FAILED

Plate Details :	122012 Sharjah Private
Chassis No :	WDB46324117114144
Vehicle Make :	MERCEDES
Vehicle Model :	G500
Vehicle Class :	Light Vehicle
Body Type :	STATION
Fuel :	Benzene
Color :	Blue
Drive Direction :	--
Dimensions : (H x W x L) :	-- x -- x --
Current Odometer :	163502 Kms.
Origin :	Germany
Model Year :	1999
Gear Type :	--
Engine Size :	3000 CC
Engine No :	NO
Horse Power :	296
Axles No :	2
Cylinders :	8
No Of Doors :	4
No Of Seats :	5
G. V. W. :	Empty Weight : 1800 Kgs. 2300 Kgs.

Certificate Number :	1-TAM-2021-14944984
Inspection Date :	05-09-2021
Certificate Print Date :	05-09-2021
Services :	Renewal Test
Vehicle Testing Partner :	Tamam
Vehicle Testing Center :	Tamam Vehicles Testing
Total Time Taken :	16 min 15 sec
Appointment Ref Number :	--
Start Time :	16:20
End Time :	16:36
Lane :	07
Token No. :	169
Attempt :	1
Prints No. :	1

## Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
5 %	7 %	26 %	0.38 %
Vehicle on Petrol HC Reading			
82 PPM VOL			

## Inspection Findings

Defects	Issue	Severity
Warning triangle	Missing	Major
Tire FRONT RHS & REAR RHS CRACK	Cracked	Major
Tire REAR LHS EXPIRED 2015	Date of manufactured tampered or expired	Major

Discrepancies	Old Value	New Value	Verified
Engine Size Discrepancy in Engine Size	3000	5000	

Inspection Remarks: CHASSIS RUST PROOFED // FRONT BULKHEAD REPAIRED // FRONT NUMBER PLATE FIX PROPERLY

## Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
2174	Cash	14944984	AED 170 Collected on 05/09/2021
Parking Slot No	Service Name	Attempt	Received by
--	Renewal Test	1	KHALED MAHMOUD SALEH ABDELAZIZ ELSAYED

- This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.
- Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتمد بهذه الشهادة لتي عمليات أخرى بما في ذلك أعراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.