



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Aug 2022, 13:19:15
Transaction Number	68060888 (CC10008)	Queue Number	312309



Chassis Number	1GKKV8ED8BJ318602
Engine Number	
Vehicle Class	Car
Manufacturer	GMC
Model	Acadia
Model Year	2011
Color	White
Mileage	222225 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
03 Engine Condition		المحرك
03.A Visual Engine Condition	MINOR OIL LEAK REFITTED	حالة المحرك النظري
03.B Mount	MOUNT RUBBER CUT	كرسي
04 Transmission Condition		الجير
04.A Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
06 Lights		الاضاءة

DEFECT	REMARKS	
06.A Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
06.B Head Light	RIGHT SIDE LOW,HIGH BEAM NOT WORKING	الاضاءة الرئيسية
06.C Fog light	RIGHT SIDE NOT WORKING	كشاف الضباب
07 Body		جسم المركبة
07.A Fenders	REPAIRED,REPAINTED & FRONT REFITTED	مدكار
07.B Bonnet	PORTION REPAIRED,REPAINTED	غطاء المحرك
07.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
07.D Roof	ROOF RAIL REPAIRED,REPAINTED	السقف
07.E Pillars	PILLAR OUTER PANEL REPAIRED,REPAINTED	القوائم
07.F Doors	REPAIRED,REPAINTED	أبواب
07.G Trunk	REPAIRED,REPAINTED	صندوق
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSHES CUT	ازرع
08.B Ball Joint	BOOT CUT	مفصل كروي
08.C Other	STABILIZER LINK BOOT CUT	اخرى
09 Chassis Condition		الشاسي
09.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.