



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	16 Nov 2022, 16:55:37
Transaction Number	15606040 (CC10006)	Queue Number	624509



Chassis Number	2LMDJ8JKOFBL29866
Engine Number	
Vehicle Class	Car
Manufacturer	Lincoln
Model	MKX
Model Year	2015
Color	White
Mileage	115896 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY MINOR DENT,SCRATCHES,	الصبغ
01.B Rusty	UNDER BODY PARTS , SUSPENTION GETTING RUSTY	صدأ
01.C Floor	BACK PANEL REPAIRED	الارضية
01.D Sign of back accident		وجود مؤشر لحادث في الخلف
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OK	حالة الجير النظري
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2018 CRACKED,	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2018 CRACKED,	الاطار الخلفي
04 Interior Condition		الحاله الداخليه
04.A Sunroof	NOT WORKING PROPERLY	فتحت سقف
04.B AC Condition	LOW COOLING	المكيف
05 Steering Condition		المقود

DEFECT	REMARKS	
05.A Axle	BOOT LEAKING	اكسلات
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Engine Condition		المحرك
08.A Visual Engine Condition	OK	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.