

Queue Number 2361743

Transaction Date 06 May 2026, 16:44:14

Site Name
840 - Emirates AuctionsTransaction Number
84180360 (CC10009) (CC10009)

Vehicle Details

Chassis Number JTEHJ09J33*****
 Specification GCC Specification
 Make Toyota
 Model Land Cruiser
 Model Year 2003
 Color Silver
 Mileage 286683 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION FADED, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS THICK RUST PROOF, NOT VISIBLE	الارضية
01.D Bonnet	LEVER DAMAGED	غطاء المحرك
01.E Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED	وجود مؤشر لحادث في المقدمة
01.F Vehicle Color	GOLDEN	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT BOTH SIDE CHASSIS END BRACKET REPAIRED , BOTH SIDE THICK RUST PROOFED, MUDDY PORTION RUSTY	الشاسيه
02.B Chassis Number	THICK RUST PROOFED, CHECKED ONLY PLATE	رقم القاعدة

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK REFITTED GETTING RUSTY MUDDY	الحالة النظرية للمحرك
------------------------------	---------------------------------------	-----------------------

04 Exhaust System

نظام العادم

04.A Other	CUT REWELDED	اخرى
04.B Catalytic Converter	MISSING	دبة البيئة

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK REFITTED JERKING MUDDY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	EXPIRED CRACKED DAMAGED	الاطار الامامي
06.B Rear Tyre	EXPIRED CRACKED DAMAGED	الاطار الخلفي
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	LOWER ARM BUSHES CUT	ازرع
07.C Other	SUSPENSION REFITTED	اخرى
07.D Ball Joint	BOOT CUT	مفصل كروي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخليه
09.A Other	INNER PARTS GETTING RUSTY	اخرى
09.B AC Condition	NOT WORKING	المكيف
09.C Power Window Switch And Glass	REAR RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
09.D Dash Board	PORTION LOOSE WORN OUT, PORTION CRACKED	لوحة القيادة
09.E Roof Ceiling	LOOSE	بطانه السقف
09.F Odometer reading	FADED NOT VISIBLE PROPERLY	قراءة عداد المسافات
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae