CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	3025467
Transaction Date	23 Nov 2026, 15:53:21
Site Name	840 - Emirates Auctions
Transaction Number	89406851 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WP1ZZZ92ZD*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2013
Color	White
Mileage	171022 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS FULLY COVERED	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	AUTO SWITCH NOT WORKING PROPERLY,	صندوق
01.I Sign of back accident	BACK PANEL REAPIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS FULLY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK REFITTED SHAKING	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DRIVER SEAT BACK COVER PORTION DAMAGED	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LEFT SIDE LENS FADED	الاضاءة الرئيسية
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK,ADJUSTMENT PORTION MISSING	المكيف
08.B Dash Board	LEATHER PORTION WORN OUT LOOSE	لوحة القياده
08.C Sun Visor	RIGHT SIDE BRACKET DAMAGED	حاجب الشمس
08.D Door Panel	REAR BOTH SIDE CIGARETTE CONSOLE BOX STUCK	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Sunroof	NOT WORKING	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae