



TEST CERTIFICATE

| | | | |
|--------------------|------------------------------|------------------|------------------------------|
| Site Number | 840-Emirates Auctions | Transaction Date | 18 Jan 2022, 15:07:23 |
| Transaction Number | 98839908 (CC10006) | Queue Number | 312309 |



| | |
|------------------|--------------------------|
| Chassis Number | MDHBN7AD7FG721484 |
| Engine Number | |
| Vehicle Class | Car |
| Manufacturer | Nissan |
| Model | Sunny |
| Model Year | 2015 |
| Color | Silver |
| Mileage | 167129 Km |
| Fuel Type | Petrol |
| No. Of Cylinders | 4 |
| Specification | GCC Specification |

| DEFECT | REMARKS | |
|---|--------------------------------|----------------------------|
| 01 Body | | جسم المركبة |
| 01.A Floor | LEFT SIDE QUATER PANEL DENT | الارضية |
| 01.B Paint | DENTS & SCRATCHES ON BODY | الصبغ |
| 01.C Bumper | MISALIGN & PORTION CRACKED | دعامية |
| 01.D Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 02 Engine Condition | | المحرك |
| 02.A Visual Engine Condition | OK | حالة المحرك النظري |
| 03 Interior Condition | | الحالة الداخليه |
| 03.A AC Condition | OK | المكيف |
| 03.B Steering Wheel and control buttons | COVER CRACKED | عجلة القيادة وازرار التحكم |
| 04 Lights | | الاضاءة |
| 04.A Warning Light | WARNING LIGHT ON IN DISPLAY | ضوء تحذير |
| 04.B Head Light | LENS FADED | الاضاءة الرئيسية |
| 05 Tires and Rims Condition | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2020 | الاطار الامامي |

| DEFECT | REMARKS | |
|----------------------------------|----------------|-------------------|
| 05.B Rear Tyre | BOTH SIDE 2020 | الاطار الخلفي |
| 06 Seats Condition | | المقاعد |
| 06.A Seat Condition | COVER DAMAGED | حالة المقاعد |
| 07 Transmission Condition | | الجير |
| 07.A Road Test | NOT CHECK | فحص علي الطريق |
| 07.B Visual Gear Box Condition | OK | حالة الجير النظري |
| 08 Chassis Condition | | الشاسي |
| 08.A Chassis | OK | الشاسيه |

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.