CAR CHECK

شهادة فحص مركبة
**Vehicle Test Certificate**

| | |
|---|---|
| Queue Number | 2949549 |
| Transaction Date | 07 Nov 2026, 12:40:32 |
| Site Name | 840 - Emirates Auctions |
| Transaction Number | 46268621 (CC10009) (CC10019) |




**Vehicle Details**

| | |
|---|---|
| Chassis Number | WDB2201731******* |
| Specification | Imported |
| Make | Mercedes |
| Model | S 55 |
| Model Year | 2001 |
| Color | White |
| Mileage | 151449 Km |
| Fuel Type | Petrol |
| Transmission Type | |
| No. Of Cylinders | 8 |

| Condition | Remarks | الحالة |
|---|---|---|
| **01 Body** | | جسم المركبة |
| 01.A Fenders | FRONT BOTH SIDE REFITTED | مدكار |
| 01.B Paint | BODY REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES, | الصبغ |
| 01.C Rusty | UNDER BODY PARTS GETTING RUSTY | صدأ |
| 01.D Floor | FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY | الارضية |
| 01.E Bumper | MISALIGN,PORTION DAMAGED | دعامية |
| 01.F Bonnet | REFITTED | غطاء المحرك |
| 01.G Trunk | MISALIGN | صندوق |
| 01.H Sign of front accident | FRONT BUMPER FRAME BULK HEAD REPAIRED | وجود مؤشر لحادث في المقدمة |
| **02 Chassis Condition** | | الشاصي |
| 02.A Chassis | FRONT RIGHT SIDE OUTER SLIGHTLY BEND BOTH SIDE COVERED CHECKED VISIBLE AREA ONLY | الشاسيه |
| **03 Engine Condition** | | المحرك |
| 03.A Engine Visual Condition | OIL LEAK REFITTED SHAKING GETTING RUSTY | الحالة النظريه للمحرك |
| **04 Transmission Condition** | | الجير |
| 04.A Gear Box Visual Condition | MINOR OIL LEAK REFITTED GETTING RUSTY | الحالة النظريه للجير |
| 04.B Road Test | NOT CHECKED | فحص علي الطريق |

| Condition | Remarks | الحالة |
|---|---|---|
| **05 Tires and Rims Condition** | | الاطارات |
| 05.A Front Tyre | BOTH SIDE 2026 | الاطار الامامي |
| 05.B Rear Tyre | BOTH SIDE 2026 | الاطار الخلفي |
| 05.C Rims Condition | MINOR SCRATCHES | حالة الجنوط |
| **06 Lights** | | الاضاءة |
| 06.A Head Light | LENS FADED | الاضاءة الرئيسية |
| **07 Suspension System** | | ممتص الصدمات |
| 07.A Shock Absorber | AIT MATICK NOT WORKING PROPERLY | ممتص الصدمات |
| **08 Interior Condition** | | الحاله الداخليه |
| 08.A Mirror | CENTER MIRROR PORTION LOOSE | المرايا |
| 08.B AC Condition | OK | المكيف |
| 08.C Sun Visor | BOTH SIDE COVER MIRROR ,MISSING ,PORTION DAMAGED | حاجب الشمس |
| 08.D Steering Wheel and control buttons | WORN OUT | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
**carcheck.ae/certificate**

## Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

## الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
**wecare@carscheck.ae**