



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **25 May 2023, 17:09:05**
 Transaction Number **64290948 (CC10008)** Queue Number **726435**



Chassis Number **4T4BF3EK6AR020042**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **Toyota**
 Model **Camry**
 Model Year **2010**
 Color **Red**
 Mileage **336516 Miles**
 Fuel Type **Petrol**
 No. Of Cylinders **4**
 Specification **Imported**

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Windshield	FRONT CRACKED	زجاج
01.B Paint	BODY REPAINTED PORTION REPAIRED, PAINT FADED, DENT, SCRATCHES, PORTION RUSTY	الصبغ
01.C Bonnet	REFITTED	غطاء المحرك
01.D Fenders	FRONT REFITTED & REAR RIGHT DAMAGED	مدكار
01.E Floor	PORTION DENT	الارضية
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Other	FRONT FENDER FRAME, RADIATOR SUPPORT, BULK HEAD , BUMPER FRAME REPAIRED	اخرى
01.H Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2021 CRACKED	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021 CRACKED	الاطار الخلفي
02.C Rims Condition	RIMS DENT, SCRATCHES	حالة الجنوط
03 Interior Condition		الحالة الداخلية
03.A Dash Board	PORTION DAMAGED	لوحة القيادة

DEFECT	REMARKS	
03.B AC Condition	NOT CHECKED	المكيف
03.C Mirror	CENTER MIRROR MISSING	المرآيا
03.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
03.E Roof Ceiling	PORTION DAMAGED	بطانة السقف
04 Engine Condition		المحرك
04.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED	حالة المحرك النظري
04.B Other	COMPUTER UPPER COVER MISSING &AIR FILTER INTAKE BOX DAMAGED	اخرى
04.C Mount	MOUNT BUSHES CRACKED	كرسي
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	NOT CHECKED , OIL LEAK	حالة الجير النظري
05.B Gear Box Mount	MOUNT BUSHES CRACKED	كرسي الجير
06 Suspension System		ممتص الصدمات
06.A Arms	LOWER ARM BUSHES CRACKED	ازرع
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك ووطنابير الفرامل
08 Chassis Condition		الشاسي
08.A Chassis	FRONT BOTH SIDE CHASSIS END REPAIRED& RIGHT SIDE OILLY MUDDY	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.